



theTree
by **PROVIDENT**

OFF MAGADI MAIN ROAD, BANGALORE

Homes cradled by trees

Construction Status – Dec 2017

Building 1



Building 1A - Internal Painting, Plumbing, Electrical work in progress



Building 1B - Internal Painting, Plumbing, Electrical work in progress



Building 1C - Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Building 1 overall view

Building 2



Building 2A - Internal Painting, Plumbing, Electrical work in progress



Building 2B - Internal Painting, Plumbing, Electrical work in progress



Building 2C - Internal Painting, Plumbing, Electrical work in progress



Building 2D - Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress




Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Internal Painting, Plumbing, Electrical work in progress



Building 2 overall view



Clubhouse



Swimming pool

Tree Marketing Progress Report - December 2017									
S. No	Activities	Wings/Blocks							As On 31.12.2017
		Building 1			Building 2				
		A	B	C	A	B	C	D	
A		Lower Basement Floor							
1	Earth Work Excavation	100%	100%	100%	100%	100%	100%	100%	
2	Plain Cement Concrete	100%	100%	100%	100%	100%	100%	100%	
3	Raft/Footing Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Raft/Footing Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Retaining Wall Concrete (1st lift)	NA	NA	NA	100%	100%	100%	100%	
6	Retaining Wall Concrete (2nd lift)	NA	NA	NA	100%	100%	100%	100%	
7	Grade Slab concreting	NA	NA	NA	100%	100%	100%	100%	
8	Block work	NA	NA	NA	100%	100%	100%	100%	
B		UPPERBASEMENT FLOOR							
1	Column Concrete (up to 1st slab - Upper basement floor)	NA	NA	NA	100%	100%	100%	100%	
2	Upper basement Floor Slab Shuttering	NA	NA	NA	100%	100%	100%	100%	
3	Upper basement Floor Slab Reinforcement	NA	NA	NA	100%	100%	100%	100%	
4	Upper basement Floor Slab Concrete	NA	NA	NA	100%	100%	100%	100%	
5	Block work	NA	NA	NA	100%	100%	100%	100%	
6	Grade Slab concreting	NA	NA	NA	100%	100%	100%	100%	
C		GROUND FLOOR							
1	Column Concrete (up to 1st slab - Ground floor)	100%	100%	100%	100%	100%	100%	100%	
2	Ground Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Ground Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Ground Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	55%	55%	
8	Internal Painting	80%	80%	90%	30%	30%	20%	20%	
9	Plumbing	70%	70%	80%	40%	40%	40%	40%	
10	Electrical	72%	70%	80%	40%	40%	40%	40%	
D		FIRST FLOOR							
1	Column Concrete (Ground floor -First floor)	100%	100%	100%	100%	100%	100%	100%	
2	First Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	First Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	First Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	60%	60%	95%	35%	35%	15%	10%	
9	Plumbing	60%	60%	85%	50%	50%	50%	50%	
10	Electrical	60%	60%	85%	50%	50%	50%	50%	
E		SECOND FLOOR							
1	Column Concrete (First floor - Second floor)	100%	100%	100%	100%	100%	100%	100%	
2	Second Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Second Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Second Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	55%	67%	95%	30%	30%	15%	10%	
9	Plumbing	66%	65%	85%	50%	50%	50%	51%	
10	Electrical	66%	65%	85%	50%	50%	50%	51%	
F		THIRD FLOOR							
1	Column Concrete (Second floor-Third floor)	100%	100%	100%	100%	100%	100%	100%	
2	Third Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Third Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Third Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	32%	56%	95%	30%	30%	20%	10%	
9	Plumbing	66%	65%	85%	52%	52%	52%	50%	
10	Electrical	66%	65%	85%	52%	52%	52%	50%	
G		FOURTH FLOOR							
1	Column Concrete (Third floor-Fourth floor)	100%	100%	100%	100%	100%	100%	100%	
2	Fourth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Fourth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Fourth Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	34%	65%	95%	30%	30%	15%	10%	
9	Plumbing	67%	70%	85%	52%	52%	52%	45%	
10	Electrical	67%	70%	85%	52%	52%	52%	45%	

TREE MARKETING PROGRESS REPORT - December2017									
S. No	ACTIVITIES	WINGS/BLOCKS							As On 31.12.2017
		Building 1			Building 2				
		A	B	C	A	B	C	D	
H	FIFTH FLOOR								
1	Column Concrete (Fourth floor-Fifth Floor)	100%	100%	100%	100%	100%	100%	100%	
2	Fifth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Fifth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Fifth Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	45%	68%	95%	35%	35%	15%	10%	
9	Plumbing	67%	70%	85%	52%	52%	52%	45%	
10	Electrical	67%	70%	85%	52%	52%	52%	45%	
I	SIXTH FLOOR								
1	Column Concrete (Fifth Floor-Sixth Floor)	100%	100%	100%	100%	100%	100%	100%	
2	Sixth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Sixth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Sixth Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	45%	68%	95%	35%	35%	15%	10%	
9	Plumbing	67%	70%	85%	52%	52%	52%	45%	
10	Electrical	67%	70%	85%	52%	52%	52%	45%	
J	SEVENTH FLOOR								
1	Column Concrete (Sixth Floor-Seventh Floor)	100%	100%	100%	100%	100%	100%	100%	
2	Seventh Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Seventh Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Seventh Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	45%	75%	95%	35%	35%	15%	10%	
9	Plumbing	67%	72%	85%	58%	58%	40%	35%	
10	Electrical	67%	72%	85%	58%	58%	40%	35%	
K	EIGHTH FLOOR								
1	Column Concrete (Seventh Floor-Eighth Floor)	100%	100%	100%	100%	100%	100%	100%	
2	Eighth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Eighth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Eighth Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	45%	75%	95%	35%	35%	15%	10%	
9	Plumbing	67%	72%	85%	58%	58%	40%	35%	
10	Electrical	67%	72%	85%	58%	58%	40%	35%	
M	NINTH FLOOR								
1	Column Concrete (Eighth Floor-Ninth Floor)	100%	100%	100%	100%	100%	100%	100%	
2	Ninth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Ninth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Ninth Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	45%	75%	95%	35%	35%	15%	10%	
9	Plumbing	67%	72%	85%	58%	58%	40%	35%	
10	Electrical	67%	72%	85%	58%	58%	40%	35%	
N	TENTH FLOOR								
1	Column Concrete (Ninth Floor-Tenth Floor)	100%	100%	100%	100%	100%	100%	100%	
2	Tenth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%	100%	
3	Tenth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%	100%	
4	Tenth Floor Slab Concrete	100%	100%	100%	100%	100%	100%	100%	
5	Block work	100%	100%	100%	100%	100%	100%	100%	
6	Internal Plastering	100%	100%	100%	100%	100%	100%	100%	
7	Flooring Tiles	100%	100%	100%	100%	100%	100%	100%	
8	Internal Painting	45%	72%	95%	50%	50%	15%	10%	
9	Plumbing	68%	72%	85%	58%	58%	40%	35%	
10	Electrical	68%	72%	85%	58%	58%	40%	35%	

Provident Housing Limited, 130/1, Ulsoor Road, Bangalore - 560 042,
Call - 080 – 67724001, Email: crm@puravankara.com