

PROVIDENT™


YOUR HOME IN THE CLOUDS.

324 classy homes on a hilltop.



PROVIDENT
Skyworth
Derebail, Mangalore

Construction Status – Dec 2017



B Block



C Block



D Block



E Block



F Block



G Block



Water Storage

PROVIDENT SKYWORTH							
WORK PROGRESS REPORT - Dec '17							
SKYWORTH MARKETING PROGRESS REPORT -December 2017-(As On 31.12.2017)							
S. No	ACTIVITIES	WINGS					
		B	C	D	E	F	G
A	BASEMENT FLOOR						
1	Earth Work Excavation	NA	NA	NA	100%	100%	100%
2	Plain Cement Concrete	NA	NA	NA	100%	100%	100%
3	Raft/Footing Reinforcement	NA	NA	NA	100%	100%	100%
4	Raft/Footing Concrete	NA	NA	NA	100%	100%	100%
5	Grade Slab Concreting	NA	NA	NA		50%	30%
6	Block Work	NA	NA	NA			
B	FIRST SLAB- GROUND FLOOR						
1	Earth Work Excavation	100%	100%	100%	NA	NA	NA
2	Plain Cement Concrete	100%	100%	100%	NA	NA	NA
3	Raft/Footing Reinforcement	100%	100%	100%	NA	NA	NA
4	Raft/Footing Concrete	100%	100%	100%	NA	NA	NA
5	Grade Slab Concreting	20%			NA	NA	NA
6	Column Concrete (Basement Floor - Ground Floor Slab)	NA	NA	NA	100%	100%	100%
7	Ground Floor Slab Shuttering	NA	NA	NA	100%	100%	100%
8	Ground Floor Slab Reinforcement	NA	NA	NA	100%	100%	100%
9	Groundfloor Slab Concrete	NA	NA	NA	100%	100%	100%
10	Block Work	95%					
11	Electrical Work	60%	NA	NA	50%	50%	50%
C	SECOND SLAB - FIRST FLOOR						
1	Column Concrete (Ground Floor - Up To First Floor)	100%	100%	100%	100%	100%	100%
2	First Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	First Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	First Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	100%	100%	100%
6	Internal Plaster	100%	100%	100%	76%	100%	100%
7	Electrical Work	78%	50%	50%	50%	50%	50%
D	THIRD SLAB - SECOND FLOOR						
1	Column Concrete (First Floor - Second Floor)	100%	100%	100%	100%	100%	100%
2	Second Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Second Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Second Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	100%	100%	100%
6	Internal Plastering	100%	100%	100%	100%	95%	100%
7	Electrical Work	50%	50%	50%	50%	50%	50%
E	FOURTH SLAB - THIRD FLOOR						
1	Column Concrete (Second Floor-Third Floor)	100%	100%	100%	100%	100%	100%
2	Third Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Third Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Third Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	100%	100%	100%
6	Internal Plastering	100%	100%	100%	100%	95%	100%
7	Electrical Work	50%	50%	50%	50%	50%	50%

PROVIDENT SKYWORTH							
WORK PROGRESS REPORT - Dec '17							
SKYWORTH MARKETING PROGRESS REPORT -December 2017-(As On 31.12.2017)							
S. No	ACTIVITIES	WINGS					
		B	C	D	E	F	G
F	FIFTH SLAB - FOURTH FLOOR						
1	Column Concrete (Third Floor-Fourth Floor)	100%	100%	100%	100%	100%	100%
2	Fourth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Fourth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Fourth Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	100%	100%	100%
6	Internal Plastering	100%	100%	100%	100%	95%	100%
7	Electrical Work	50%	50%	60%	50%	50%	50%
G	SIXTH SLAB - FIFTH FLOOR						
1	Column Concrete (Fourth Floor-Fifth Floor)	100%	100%	100%	100%	100%	100%
2	Fifth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Fifth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Fifth Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	100%	100%	100%
6	Internal Plastering	100%	100%	100%	10%	90%	100%
7	Electrical Work	50%	50%	50%	16%	50%	50%
H	SEVENTH SLAB - SIXTH FLOOR						
1	Column Concrete (Fifth Floor-Sixth Floor)	100%	100%	100%	100%	100%	100%
2	Sixth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Sixth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Sixth Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	100%	100%	100%
6	Internal Plastering	100%	100%	100%	36%	90%	100%
7	Electrical Work	50%	50%	50%	50%	50%	50%
I	EIGHTH SLAB - SEVENTH FLOOR						
1	Column Concrete (Sixth Floor-Seventh Floor)	100%	100%	100%	100%	100%	100%
2	Seventh Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Seventh Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Seventh Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	85%	95%	100%
6	Internal Plastering	100%	100%	100%	10%	80%	100%
7	Electrical Work	50%	50%	50%	50%	50%	50%
J	NINETH SLAB - EIGHTH FLOOR						
1	Column Concrete (Seventh Floor-Eighth Floor)	100%	100%	100%	100%	100%	100%
2	Eighth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Eighth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Eighth Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	100%	95%	100%
6	Internal Plastering	100%	100%	100%	10%	80%	100%
7	Electrical Work	50%	50%	50%	50%	50%	50%

PROVIDENT SKYWORTH							
WORK PROGRESS REPORT - Dec '17							
SKYWORTH MARKETING PROGRESS REPORT -December 2017-(As On 31.12.2017)							
S. No	ACTIVITIES	WINGS					
		B	C	D	E	F	G
K	TENTH SLAB - NINTH FLOOR						
1	Column Concrete (Eighth Floor-Ninth Floor)	100%	100%	100%	100%	100%	100%
2	Ninth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Ninth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Ninth Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	90%	95%	100%
6	Internal Plastering	100%	100%	100%		33%	100%
7	Electrical Work	50%	50%	50%	50%	50%	50%
L	ELEVENTH SLAB - TENTH FLOOR						
1	Column Concrete (Ninth Floor-Tenth Floor)	100%	100%	100%	100%	100%	100%
2	Tenth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Tenth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Tenth Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	43%	95%	100%
6	Internal Plastering	100%	100%	90%		33%	100%
7	Electrical Work	50%	50%	50%	16%	14%	50%
M	TWELVTH SLAB - ELEVENTH FLOOR						
1	Column Concrete (Tenth Floor-Eleventh Floor)	100%	100%	100%	100%	100%	100%
2	Eleventh Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Eleventh Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Eleventh Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	100%	100%	28%	75%	100%
6	Internal Plastering	100%	25%	30%			100%
7	Electrical Work	50%	50%	50%	16%	14%	50%
N	THIRTEENTH SLAB - TWELVETH FLOOR						
1	Column Concrete (Eleventh Floor- Twelveth Floor)	100%	100%	100%	100%	100%	100%
2	Twelveth Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Twelveth Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Tweleth Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	100%	90%	85%	12%	75%	100%
6	Internal Plastering	100%					100%
7	Electrical Work	50%	50%	50%	14%	14%	50%
O	FOURTHEENTH SLAB - TERRACE FLOOR						
1	Column Concrete (Twelveth Floor-Terrace Floor)	100%	100%	100%	100%	100%	100%
2	Terrace Floor Slab Shuttering	100%	100%	100%	100%	100%	100%
3	Terrace Floor Slab Reinforcement	100%	100%	100%	100%	100%	100%
4	Terrace Floor Slab Concrete	100%	100%	100%	100%	100%	100%
5	Block Work	90%	80%	80%			
6	Plastering	70%					
6	Electrical Work	14%	14%	14%	14%	14%	14%

Provident Housing Limited, 130/1, Ulsoor Road, Bangalore - 560 042,
Call - 080 – 67724001, Email: crm@puravankara.com