PROVIDENT



Construction Updates August 2022



Dear Esteemed Customer,

Greetings from Provident

It gives us immense pleasure to update you through this edition of Provident Newsletter and provide you with the latest information about your home in Provident Kenworth. As we move ahead, we at Provident sincerely thank you for your continual faith and trust reposed in the brand.

We are happy to inform you that the construction and infrastructure works at the site is progressing well. We thank you for your understanding that is a construction site with extensive debris, heavy vehicular movement, uneven surfaces and hence keeping in mind your safety, visits to this site is restricted. You may seek prior approval and we can accommodate the scheduled visit from your respective banker.

We are grateful for your kind cooperation.

Team Provident Kenworth





Provident Kenworth

Inner Ring Road, Hyderabad



Construction Updates

Overall view



Actual site photograph

TOWER STATUS

Finishing work in progress.



MILESTONES ACHIEVED

- Door fixing 120 flats completed.
- Internal door 120 flats completed.
- External 1st paint 100% completed.
- SD fixing 120 flats completed.
- Lift gladding service lift completed.
- Bison board work 120 flats completed.
- Stilt floor IPS work completed.



UPCOMING MILESTONES

• Completion of finishing work.





Actual site photograph

TOWER STATUS

 Stilt & terrace floor MEP works in progress.



MILESTONES ACHIEVED

- External plaster completed 100% completed.
- Toilet dado & flooring 230 flats completed.
- Flooring tile completed 230 flats.
- 1st coat & 2nd coat putty completed 230 flats.
- External primer 100% completed, 1st coat paint 100% completed.



UPCOMING MILESTONES

• Completion of finishing work.





Actual site photograph

TOWER STATUS

Finishing work in progress.



MILESTONES ACHIEVED

- External plaster 100% completed.
- 1st & 2nd coat putty work complete 120 flats completed.
- Tile work completed 120 flats.
- Toilet dado & flooring 120 flats completed.



UPCOMING MILESTONES

• Completion of finishing work.





Actual site photograph

TOWER STATUS

- Door fixing work 120 flats completed.
- Bison board work 120 completed & false ceiling work 120 flats completed.



MILESTONES ACHIEVED

- Service lift & Passenger Lift completed.
- Stilt floor Screed completed.
- Door fixing work 120 flats completed.
- Bison board work 120 completed & false ceiling work 120 flats completed.



UPCOMING MILESTONES

• Possession.





Actual site photograph

TOWER STATUS

Finishing work in progress.



MILESTONES ACHIEVED

- 2nd coat putty 120 flats completed.
- Lift errection completed.
- External primer 100% completed.
- Windows, door fixing 120 flats completed.
- Kitchen counter 120 flats completed.



UPCOMING MILESTONES

• Completion of finishing work.





Actual site photograph

TOWER STATUS

Common area works in progress.



MILESTONES ACHIEVED

- Tile work completed 120 flats.
- Toilet dado & flooring 120 flats completed.
- Putty completed 120 flats.
- 2nd coat putty work completed 120 flats.
- Internal plastering 100% completed.
- Service lift gladding work completed.
- External primer 100% completed.
- External 1st painting 100% completed.
- Ips concrete work completed.



UPCOMING MILESTONES

• Completion of common area works.





Actual site photograph

TOWER STATUS

- Wall & ceiling 2nd coat putty work in progress.
- External wall primer work in progress.
- Tile flooring, dado work in progress.
- Hand rail fabrication work in progress.
- Windows, sliding door, door fixing work in progress.



MILESTONES ACHIEVED

- 1st coat putty completed 120 flats.
- · 2nd coat putty completed 99 flats.
- Toilets & utility white wash 100% completed.
- External primer 96% completed.
- Basement ips flooring completed 95%.
- Tile flooring completed 100 flats.



UPCOMING MILESTONES

- Flooring Tile 100% completion.
- External primer 100% completion.
- Basement IPS flooring 100% completion.





Actual site photograph

TOWER STATUS

- External primer in progress.
- Tile laying works in progress.
- Windows, sliding door fixing in progress.



MILESTONES ACHIEVED

- Flats wall & ceiling plaster completed 200 flats.
- Toilet waterproofing completed 200 flats.
- Toilet screed completed 200 flats.
- External plastering completed 100% completion.
- Internal wall plaster completed 200 flats.
- External wall primer 85% completed.
- 1st coat putty 200 flats.
- Terrace waterproofing & concrete 20 flats completed.



UPCOMING MILESTONES

• Completion of vitrified flooring – 200 flats.



Amenity 2



Actual site photograph

TOWER STATUS

- Soil backfilling works in progress.
- Terrace slab concrete completed.
- Part 1,2 & 3 basement 1 slab completed.
- Part 1, 2 & 3 ground floor, 1st floor, 2nd floor slab & 3rd floor & terrace slab completed.



Contact Us PROVIDENT

Site Office:

Provident Kenworth

6-1-33, Inner Ring Rd, Shivrampalli Village, Shivarampally Jagir, Hyderabad, Telangana 500052

Regional Office:

Provident Housing Limited No.8, Ulsoor Road, Bengaluru- 560 042 Tel: 080-44555544

Email: crm@providenthousing.com (Subject line – Project name/ unit number)

Call Us: +91 - 80-67724001 / 1860 208 0000

Web: www.providenthousing.com