PROVIDENT



Construction Updates
April 2023



Dear Esteemed Customer,

Greetings from Provident

It gives us immense pleasure to update you through this edition of Provident Newsletter and provide you with the latest information about your home in Provident Kenworth. As we move ahead, we at Provident sincerely thank you for your continual faith and trust reposed in the brand.

We are happy to inform you that the construction and infrastructure works at the site is progressing well. We thank you for your understanding that is a construction site with extensive debris, heavy vehicular movement, uneven surfaces and hence keeping in mind your safety, visits to this site is restricted. You may seek prior approval and we can accommodate the scheduled visit from your respective banker.

We are grateful for your kind cooperation.

Team Provident Kenworth





Provident Kenworth

Inner Ring Road, Hyderabad



Construction Updates

Overall view

Tower 12



Actual site photograph

PROGRESS TIMELINE



TOWER STATUS

- Wall & ceiling 2nd coat putty work in progress.
- External wall painting work in progress.
- Tile flooring, dado work in progress.
- Hand rail fabrication work in progress.
- Windows, sliding door, door fixing in progress.



MILESTONES ACHIEVED

- 1st coat putty completed 120 flats.
- 2nd coat putty completed 120 flats.
- Toilets & utility white wash 100% completed.
- External primer 100% completed.
- Basement IPS flooring completed 100%.
- Tile flooring completed for 120 flats.



UPCOMING MILESTONES

 Completion of windows, sliding door, door fixing work.

Tower 13



Actual site photograph

PROGRESS TIMELINE



TOWER STATUS

- Wall & ceiling 2nd coat putty work in progress.
- External wall painting work in progress.
- Tile flooring, dado work in progress.
- Hand rail fabrication work in progress.
- Windows, sliding door, door fixing in progress.



MILESTONES ACHIEVED

- Internal wall plaster completed 200 flats.
- Vitrified tiles 200 flats completed.
- Sliding door fixed 200 flats completed.
- External wall primer 100% completed.
- 2nd coat putty 200 flats completed.
- Internal primer 180 flats completed.
- Main door 200 flats completed.
- Internal door 200 flats completed.



UPCOMING MILESTONES

 Completion of windows, sliding door, door fixing work.

Amenity 2



Actual site photograph

TOWER STATUS

- Soil backfilling works in progress.
- Terrace slab concrete completed.
- Basement block work in progress.
- UG sump structural work completed.
- Block work, sill concrete work in progress.
- Part 1,2 & 3 basement 1 slab completed.
- Part 1,2 & 3 ground floor, 1st floor, 2nd floor slab & 3rd floor & terrace slab completed.

PROGRESS TIMELINE



Contact Us



Site Office:

Provident Kenworth

6-1-33, Inner Ring Rd, Shivrampalli Village, Shivarampally Jagir, Hyderabad, Telangana 500052

Regional Office:

Provident Housing Limited No.8, Ulsoor Road, Bengaluru- 560 042 Tel: 080-44555544

Email: crm@providenthousing.com (Subject line – Project name/ unit number)

Call Us: +91 - 80-67724001 / 1860 208 0000

Web: www.providenthousing.com