

 **PROVIDENT**
DEANSGATE

Construction Updates

May 2026



Dear Esteemed Customer,

Greetings from Provident

It gives us immense pleasure to update you through this edition of Provident Newsletter and provide you with the latest information about your home in Provident Deansgate. As we move ahead, we at Provident sincerely thank you for your continual faith and trust reposed in the brand.

We are happy to inform you that the construction and infrastructure works at the site is progressing well. We thank you for your understanding that is a construction site with extensive debris, heavy vehicular movement, uneven surfaces and hence keeping in mind your safety, visits to this site is restricted. You may seek prior approval and we can accommodate the scheduled visit from your respective banker.

*We are grateful for your kind cooperation.
Team Provident Deansgate*



Provident Deansgate

IVC Road, Bengaluru



Construction Updates

Overall view

CLUSTER D (D1/N07)



Actual site photograph

CLUSTER D STATUS

- Handed over to Facility Team. Final Handing over completed.



MILESTONES ACHIEVED



UPCOMING MILESTONES

PROGRESS TIMELINE



May'26

CLUSTER D (D2/N06 to D4/N04)



Actual site photograph

PROGRESS TIMELINE



May'26

CLUSTER D STATUS

- N6 -Installation of External windows work in progress & GF, FF, SF 2nd Coat Internal putty work in progress.
- N5 –Installation of External windows work in progress , Unit-3 SF & Unit 1 GF Flooring work in progress. FF & SF 1stCoat Internal putty work completed.
- N4 –External Cladding & Flooring work completed, & 1st Coat putty work in progress.



MILESTONES ACHIEVED

- N4/D4 -Flooring is completed.

UPCOMING MILESTONES

- N5/D3 -Completion of Flooring & Installation of External windows need to be completed.
- N6/D2 –Installation of External windows need to be complete.
- N4/D4 –Installation of External windows need to be complete.

CLUSTER D (D5/N03 TO D7/N01)



Actual site photograph

PROGRESS TIMELINE



May'26

CLUSTER D STATUS

- N1-Installation of External windows work in progress & GF Flooring work in progress. External staircase granite and railing work completed.
- N2- Installation of External windows Completed & 1st Coat putty work in progress, External staircase granite and railing Work completed.
- N3-Installation of External windows Completed & 1st Coat putty work in progress, External staircase granite and railing Work completed.



MILESTONES ACHIEVED



UPCOMING MILESTONES

- N1/D7-Floor tile to be completed & Installation of External windows need to be completed.

Cluster C (C1/N14 to C4/N11)



Actual site photograph

PROGRESS TIMELINE



May'26

Cluster C STATUS

- N11 –Door installation work , Putty work & Lift work is work in progress.
- N12- Door installation work , Putty work & Lift work is work in progress.
- N-13- Door installation work , Putty work & Lift work is work in progress.
- progress.
- N14- FF& SF Door Fixing work is in progress & Lift work is work in progress.



MILESTONES ACHIEVED



UPCOMING MILESTONES

- N11/C4- Installation of Door to be complete.
- N12/C3- Installation of Door to be complete.
- N13/C2- Installation of Door to be complete.
- N14/C1- Installation of Door to be complete.

Cluster C (C5/N10 to C7/N8)



Actual site photograph

PROGRESS TIMELINE



May'26

Cluster C STATUS

- N8-Door installation work , Putty work & Lift work is work in progress.
- N9 – Door installation work , Putty work & Lift work is work in progress.
- N10-Door installation work , Putty work & Lift work is work in progress.



MILESTONES ACHIEVED



UPCOMING MILESTONES

- N8-Installation of Door need to be complete.
- N9-Installation of Door need to be complete.
- N10-Installation of Door need to be complete.

CLUSTER C (C8/S09 to C11/S12)



Actual site photograph

CLUSTER C STATUS

- S9–SF Wall Electrical work in progress.
- S10- GF plastering work in progress. SF Wall Electrical work in progress.
- S11-SF Wall Electrical work in progress.
- S12-SF wall Electrical work in progress.



MILESTONES ACHIEVED



UPCOMING MILESTONES

PROGRESS TIMELINE



May'26

CLUSTER C (C12/S13 to C14/S15)



Actual site photograph

CLUSTER C STATUS

- S13 - SF electrical work completed & Plastering need to start. Toilet waterproofing work in progress.
- S14 - SF electrical work completed & Plastering need to start. Toilet waterproofing work in progress
- S15- SF electrical work completed & Plastering need to start. Toilet waterproofing work in progress



MILESTONES ACHIEVED



UPCOMING MILESTONES

PROGRESS TIMELINE



May'26

CLUSTER A (A12/S22 to A10/S20)



Actual site photograph

CLUSTER A STATUS

- S20- GF,FF & SF Toilet plumbing work in progress.
- S21- Terrace flooring work in progress. GF,FF & SF Toilet plumbing work in progress.
- S22-Terrace flooring work completed. GF,FF & SF Toilet plumbing work in progress.



MILESTONES ACHIEVED



UPCOMING MILESTONES

- S22/A12 –Floor tiling to be completed
- S21/A11 –Floor tiling to be completed

PROGRESS TIMELINE



May'26

CLUSTER A (A06/S16 to A09/S19)



Actual site photograph

PROGRESS TIMELINE



May'26

CLUSTER A STATUS

- S16- External plastering & external cladding work completed & SF plastering work need to start.
- S17 - External plastering , external cladding work & FF Plastering completed & SF plastering work need to start.
- S18 - External plastering , external cladding work & FF Plastering completed & SF plastering work need to start.
- S19 – External plastering , External cladding work SF internal plastering work completed. Toilet waterproofing completed & plumbing work in progress.



MILESTONES ACHIEVED



UPCOMING MILESTONES

S16-Flooring work need to complete.

CLUSTER A (A01/N19 to A05/N15)



Actual site photograph

PROGRESS TIMELINE



May'26

CLUSTER A STATUS

- N15- SF internal plastering work in progress.
- N16-Front side External plastering work in progress & SF internal plastering work in progress.
- N17- Front side external plastering completed & SF internal plastering work in progress.
- N18- Front side external plastering completed & SF internal plastering work in progress.
- N19-External plastering completed & External cladding work in progress. SF internal plastering work in progress.



**MILESTONES
ACHIEVED**



**UPCOMING
MILESTONES**

CLUSTER D (D15/S08 to D12/S05)



Actual site photograph

CLUSTER D STATUS

- S5-Toilet waterproofing completed & Plumbing work in progress. Flooring work need to start.
- S6- Toilet waterproofing completed & Plumbing work in progress. Flooring work need to start.
- S7- External plastering completed & External cladding work in progress
- S8- External plastering work in progress .



MILESTONES ACHIEVED



UPCOMING MILESTONES

- S05/D12 -Floor tiling need to be complete.
- S06/D13 -Floor tiling need to be complete.
- S07/D14 -Floor tiling need to be complete
- S08/D15 -Floor tiling need to be complete

PROGRESS TIMELINE



May'26

CLUSTER D (D11/S04 to D08/S01)



Actual site photograph

PROGRESS TIMELINE



May'26

CLUSTER D STATUS

- S1-GF & FF Flooring work Completed & SF Flooring & Installation of external windows need to start. SF Screed completed & External staircase granite and railing Work completed.
- S2-GF Flooring work in progress & FF Flooring completed & SF 1st coat Putty work completed. SF Flooring & Installation of external windows need to start. External staircase granite and railing Work completed.
- S3-GF & FF Flooring work completed & FF putty work in progress. External staircase granite and railing Work completed.
- S4- FF Flooring completed. GF & SF Flooring need to start. FF putty work in progress.



MILESTONES ACHIEVED

UPCOMING MILESTONES



- S01/D8 -Floor tiling & Installation of External windows need to be completed .
- S02/D9-Floor tiling & Installation of External windows need to be completed .
- S03/D10 -Floor tiling need to be completed.
- S04/D11 -Floor tiling & Installation of External windows need to be completed .

CLUSTER B (B02/E07 to B04/E05)



Actual site photograph

CLUSTER B STATUS

- E7-GF ,FF Toilet Plumbing work in progress & Flooring need to start.
- E6-GF ,FF Toilet Plumbing work in progress & Flooring need to start.
- E5-SF Plastering work in progress.



MILESTONES ACHIEVED



UPCOMING MILESTONES

- B02/E07 –Completion of Flooring need to be done.
- B03/E06 –Completion of Flooring need to be done.

PROGRESS TIMELINE



May'26

CLUSTER B (B05/E04 to B08/E01)



Actual site photograph

CLUSTER B STATUS

- E1-SF Electrical work completed & SF Plastering work need to start.
- E2- SF Electrical work completed & Plastering work need to start.
- E3- SF Electrical work completed & Plastering work need to start.
- E4- SF Electrical work completed & Plastering work need to start.



MILESTONES ACHIEVED



UPCOMING MILESTONES

PROGRESS TIMELINE



May '26

CLUSTER B (W1/B1)



Actual site photograph

CLUSTER B STATUS

- W1-GF, FF & SF Electrical work in progress & Internal plastering need to start.



MILESTONES ACHIEVED



UPCOMING MILESTONES

PROGRESS TIMELINE



May'26

Contact Us



Site Office :

Provident Deansgate

Uganawadi circle, Devanahalli Taluk,
Bengaluru – 562110.

Regional Office :

Provident Housing Limited

No.8, Ulsoor Road, Bengaluru- 560 042

Tel: 080-4455544

Email : crm@providenthousing.com (Subject line – Project name/ unit number)

Call Us : +91 - 80-67724001 / 1 860 208 0000

Web : www.providenthousing.com

RERA Registration Number :

RERA Nos.: PRM/KA/RERA/1250/303/PR/041123/006373